

***CONTINGENCY PLANNING of AIR NAVIGATION SERVICES***

**SASI Workshop**

**Real Case**

**Incompleteness of Contingency procedures**

**( Malfunction of No-Break Generator in ACC)**

**Gerald Amar – Project Manager**

**gerald.amar@eurocontrol.int**

**[http://www.eurocontrol.int/ses/public/standard\\_page/sk\\_sesis\\_guidelines.html](http://www.eurocontrol.int/ses/public/standard_page/sk_sesis_guidelines.html)**

## Status of Power Supply System – May 2008


Power Supply Station is located near the ACC building and consists of :

- Transformer station and
- Generator station including
  - automatic generator and
  - two no-break generators.

The system was installed in 1974.

Switching boxes of PS Station supplies in ACC building:

- Main switching locker and
- UPS ( 2 pcs).



# Modernisation of Power Supply System

Over 30 years long life cycle of PS equipment:

- Upgrade of PS system and tender documentation has been accomplished by the end of 2004;
- And procurement of new equipment in 2007.
- Installation of new equipment scheduled for June 2008.
- Operation for July 2008.

## ATM Occurrence – May 2008 (1/3)

14:25 UTC - Appearance of alarm on Remote Control Unit in PS Station from UPS located in ACC building.

- Technician on duty goes to ACC building to check UPS and detects the following:
  1. Warning on UPS display:  
**<Power Supply is out of tolerance >**
  2. UPS operates on battery supply
  3. UPS autonomy - **13 minutes**

## ATM Occurrence – May 2008 (2/3)

14:30 UTC - Technician goes back to PS Station.

- He informs Technical Supervisor about the problem and then,
- he calls Head of department who is **not** accessible.

14:32 UTC – In ACC building again, Technician detects  
«UPS autonomy - 6 minutes »

and makes an **erroneous decision** to switch the PS users to stand-by UPS (n°2);

Technician on duty switch UPS No.1 on static bypass configuration and then attempted to switch the PS users to stand-by UPS No.2.

It gives passage of voltage from Generator direct to Users, without stabilization.

## Consequence

Operational facilities are exposed to high voltage over tolerance,

which cause equipment outage because of failure of AC adapters:

- Linear power suppliers,
- Radar data distributors
- and Commutation modules.

## ATM Occurrence – May 2008 (3/3)

14:35 UTC - In a few minutes collapse of:

- » three quarters of Radar Data Displays,
- » one half of Flight Data Displays,
- » all radar inputs in DPS,
- » few Controller Working Positions for Voice Communication System
- » and AFTN connection with ARO & NOTAM.

14:40 UTC - Technical Supervisor informs ATC Supervisor that problem will last at least another 30minutes.

14:45 UTC - ATC SUP decides to close FIR announcing to CFMU traffic zero.

## Actions at the OPS room

- In accordance with Contingency procedure,
  - ATCOs were instructed to switch on stand-by VHF/UHF battery stations.
  - By phone, ATC SUP
    - Contacted all neighbouring FIR and requested to widen radar picture scope to monitor traffic in conflict (if there was any).
    - Contacted the airport to stop departing traffic
- Out of any Contingency procedure:
  - an action was taken by one ATCO to switch on to nearby working VCS panel because:
  - although Stand-by VHF/UHF battery station were operating normally, the frequency coverage was reduced due terrain and particular position of conflicting traffic;
  - The ATCO continued instructing aircraft, and after that, separation was managed correctly.

***What do you think of this case ??***

***What are the causes ?***

***What went right ?***

***What went wrong ?***

## Causes (as identified by the ANSP)

No-break Generator (over 30 years in exploitation) had only undervoltage protection and **did NOT** have **OVERVOLTAGE** protection.

### **No remote monitoring of allocated UPS:**

- Only alarm: manufacturer required extra training for technicians and extra payment,
- so **15 minutes of UPS autonomy** passed quickly in running between two buildings.

## Causes (as identified by the ANSP)

Technician on duty (3 years of experience):

- forgot mobile phone;
- lost time as well as his superior was not accessible;

Loss of time put Technician under **stress situation**.

He made an erroneous decision although he had two correct options:

- to supply load (PS Users) from Mains
- or to supply Load from Mains and after that from another no-break Generator

Most important factor for this ATM occurrence is that:

- **Operational and Contingency procedures** for CNS-Power Supply System, did not consider **overvoltage** situation in that particular way.

## ***Some inputs for thinking***

**Operational** contingency went **well**,

- However, one ATCO continued control two aircraft in conflict had to use a procedure not documented in the CP;  
=>>Contingency Procedures were incomplete

**Technical** contingency procedures went **wrong**:

- Case of « Overvoltage» not foreseen;
- Time of protection from UPS lost in runs between buildings.  
=>> lack of testing procedure;  
=>> and training of technicians;
- Telephone forgot and stress:  
=>> Technicians are required to carry mobile telephones.

**Contingency is a Crisis**

- =>> Clear allocation of responsibilities;
- =>> Deciders should be always accessible;

## Conclusions

This case is a classical example of coinciding “holes” (Reason’s “Swiss Cheese” model);

However “largest hole” could cover the “whole applicable procedure”.

Difficult to foresee all situations and possibilities;

Nevertheless, we have to do our best:

- Constantly reviewing Operational and Contingency procedures;
- Testing and training of Contingency procedures;
- Maintain knowledge and practices of Operational and Technical personnel via “refreshment training”.

*From the ANSP concerned ...*

***Some Technical contingency procedures  
have been changed or created***

***Eurocontrol Guidelines for Contingency Planning, used:  
“Planning” § 7, “develop or change contingency plan(s)”.  
These Guidelines are very good material.***