


# Some **Why Go-Arounds Go Wrong**



Alex Fisher  
GAPAN

Go Around Safety Forum Brussels May  
2013  
1

# Why are Go Arounds difficult?


- Low altitude, no room for error
- High thrust, typically maximum
- Underwing engines → pitch-up
- Low speed → low aerodynamic forces
  - Thrust is (nearly) independent of speed
  - Elevator power is  $\alpha(\text{speed})^2$
  - You need about twice the elevator at 140 kt you need at 200kt
- Result: large trim changes
- Conclusion: you had better know your trim system!

# So Do You Understand your Trim?

- There are (at least) two basic different trim systems
- 'Conventional Trim', most basic trainers, C152, PA28 etc, but also Lockheed TriStar, Concorde
- 'Tailplane Trim', all Boeings since the 707, all DCs since DC8, all Airbus, but also Piper Cub and Mooneys
- These differences are rarely mentioned and are often simply not understood.




# Conventional Trim 1

## 1. Initial Condition



# Conventional Trim 2

1. Initial Condition
2. Nose-down elevator



# Conventional Trim 3



1. Initial Condition

2. Nose-down elevator

3. Nose-down trim



Column load is now zero

**Effect of trim is to relieve load**






# Tailplane Trim 1

1. Initial Condition




# Tailplane Trim 2

1. Initial Condition
2. Nose-down elevator




# Tailplane Trim 3

1. Initial Condition
2. Nose-down elevator
3. Start to trim




*Both tailplane and elevator  
rotate, so to keep total  
tail load the same....*



# Tailplane Trim 4

1. Initial Condition




2. Nose-down elevator



3. Start to trim

*Both tailplane and elevator rotate, so to keep total tail load the same....*




4. Start to relax column back to neutral




# Tailplane Trim 5

1. Initial Condition



2. Nose-down elevator



3. Start to trim

4. Start to relax column  
back to neutral

5. Trimming complete,  
column back to neutral,  
tailplane and elevator in  
line



# Trim summary

Conventional	Tailplane
Column is held in position during trimming	Column has to be relaxed during trimming
Trimmed column position reflects aircraft state: Forward high speed Back Low speed	Column is always in neutral position when in trim
Trim only relieves column load	Trim does not itself relieve column load but does provide additional load path

# Resulting Errors 1

- Failure to realise that if elevator is inadequate, *additional* power is available from the tailplane (if you think the trim is just there to relieve common load, you might not realise it actually provides *more* control power)
  - A300 Taipei
  - Pitch up incident B737 at Hurn

# Resulting Errors 2

- Failure to note tailplane position; if it is already fully nose up (typically following autopilot disconnect at low speed), there is no way the elevator will contain the pitch up from full power from underwing engines
  - B737 Amsterdam
  - A320 Perpignan

# Resulting Errors 3

- Failure to realise that loss of control in pitch is due to independent operation of the tailplane, typically due to CWS or envelope 'protection'
  - A310 upset at Orly (flap speed protection)
  - A300 accident Nagoya (inadvertent activation of go-around switches)

# Resulting Errors 4

- Failure to understand the trim process itself, with resulting in severe out of phase control inputs.
  - Personal Observation
  - B757 at Oslo.

# Conclusion

- Trimming which seems such a simple process is actually full of pitfalls
- Most pilots are never taught that differences exist between types, and many never figure it out for themselves
  - Possibly because they always follow up any elevator input with small trim inputs
- Go around, with its large trim changes often shows this lack of knowledge