

The unknown risk of a flash flood

Safety Forum – June 19th 2024



Cpt Frank BAETENS
Safety Manager – TUI Airlines Belgium

The unknown risk of a flash flood

Presentation overview:

- 1 **Introduction**
- 2 **Aim**
- 3 **Description of the Event**
- 4 **Analysis**
- 5 **Investigation**
- 6 **Conclusion**
- 7 **Recommendations**



Introduction

Introduction

- Complex relationship of climate change, global warming and extreme weather events
- One consequence is the increased risk of flash floods
- Flash floods
 - sudden and intense floods
 - within minutes of heavy rainfall and storms
 - rapid melting of snow or ice
- Significant unknown challenges impacting
 - airport operations
 - flight schedules
 - infrastructure
 - overall safety



Aim

Aim

- To reveal the consequences of flash floods on aviation operations
 - by demonstrating the facts of a real incident
 - the subsequent investigation carried out
- Presentation of a TUI fly Belgium B737-700 incident *“Collision with obstacle on runway after landing”*, where the aircraft suffered damage after hitting debris upon landing onto OUD RWY 13 (September 2nd 2023).



Archive

- December 24th 2013
 - Airbus A330 (G-VNYC), Virgin Atlantic
 - From Tobago (TTCP) to St Lucia (TLPL)
 - After 35' holding (due to weather), approach and landing on a flooded runway, the aircraft veered to the left but was kept on the runway



Description of the Event


Description of the Event

- Flight: TB7242, from LFQQ (LIL) to GMFO (OUD), Oujda airport (evening flight).
- Aircraft Information:
 - OO-JAO, B737 – 700 NG
- Actual weather reported to the crew:
 - Wind 050°10kts, Clouds: Overcast 500ft
 - Temp.: 17°, Vis.: 8000m
- Just after touch down on Rwy13 at GMFO (OUD) Oujda airport, the flight crew noticed an object looking like a large branch or small tree just left of the centerline.
- After impact, a scraping noise was heard for a few seconds.



Description of the Event


- During roll out, several master caution lights and non-normal indications popped up in the cockpit.
- After coming to a full stop, the crew decided to shut down the engines and ask for a technical inspection (on the runway) followed by a tow towards the apron.
- Damage occurred to the aircraft, debris and dirt on the runway seemed having caused the damage.



Analysis

Analysis

Airport lay out





OUD airport is situated in the northeast of Morocco, located near mountains that separate Morocco from Algeria.

Analysis

Final approach



- Steeper glide (3.4°)
- IMC



Analysis

Visual segment

- Runway became visible at about 500ft.
- Visibility below the cloud base was good.
- Runway lights partially U/S.
- Wind was light and steady from the northeast (050/10)



Analysis

Touchdown and landing roll

- Normal touchdown, obstacle observed just left of the centerline.
- A scraping noise was heard for a few seconds, deceleration was stronger than normal with autobrakes 2 selected.
- Directional control, braking and thrust reverser operation observed as normal.
- Normal engine parameters.



Analysis

Landing roll until full stop on the runway

- Several amber caution lights came on, aft cargo fire warning.
- Aircraft stopped on the runway just before taxiway V, appropriate calls to ATC and cabin were immediately performed.
- The cargo fire warning stopped by itself, a test proved the system was functional and working properly.
- The cabin crew reported all normal.



Analysis

Full stop, emergency services on the spot, decision for towing onto a parking stand

- Assistance vehicles approached the aircraft, APU started and engines shut down.
- The fire brigade reported a visible fluid leak (syst B).
- On the stand, pax disembarked via bridge.
- Found twigs, pieces of wood and other debris in the inboard leading edge devices, trailing edge flaps and all wheel wells.
- Main wheel well flooded with brown watery mud.
- A significant amount of water/mud was also present in both cargo holds, especially aft, causing damage to the pax luggage.
- Damage to the RH horizontal stabilizer leading edge.
- Several antennas on lower fuselage damaged.



Investigation

Investigation

Observations after the Event

Operational visit at OUD airport after the event:

- The drainage system can process the excess of water under normal circumstances.
- At the time of the event, an enormous amount of water had come down from the mountains, in addition to the water that was caused by heavy rainfall.
- Concrete walls and pavements appeared to be demolished.



Investigation

Observations after the Event

- The airport and surroundings drainage system could no longer absorb this amount of water.
- A massive amount of water caused a flash flood over the runway just before our landing aircraft (21:43 UTC).
- The perimeter wall was destructed close to the touchdown point of RWY 13.




Investigation

Timeline

- Two aircraft landed ahead of the TUI flight
 - Royal Air Maroc at **21:17 UTC**,
 - Air Arabia at **21:35 UTC**.
- These aircraft did not report any problems.
- The Airport authorities carried out RWY 13 inspection checks;
 - at **19:50 UTC** after the first rainfall and
 - at **21:25 UTC**.

All checks did not reveal anything particular, only some water patches were observed.

- Our plane (OO-JAO) landed at **21:43 UTC**, 8 minutes after the Air Arabia and reported that it had hit a piece of wood.



Investigation

Risk Assessment

		Probability							
		P	P1	P2	P3	P4	P5	P6	P7
Severity		S							
S6		C21	C27	B33	A45	A57	A69	A89	
S5		D15	C19	C23	B29	B35	A48	A61	
S4		E10	D12	D14	C19	C26	B35	B44	
S3		E6	E8	E10	D13	D18	C23	C28	
S2		E3	E5	E7	E9	E11	D13	D15	
S1		E1	E2	E3	E4	E5	E6	E7	

The Event Probability : P2 (Rare)
 The Event Severity : S5 (Hazardous)
 The overall Risk Level : Medium (C19)

A	EXTREME (45-89)	MANAGE URGENTLY
B	High (29-44)	MANAGE URGENTLY
C	Medium (19-28)	MANAGE ACTIVELY
D	Low (12-18)	MONITOR & REVIEW
E	Minimal (1-11)	MONITOR & RECORD

Conclusion

Conclusion

- The root cause of the event can be described as a “flash flood”.
- Debris and dirt were carried on the runway by a large flow of water that caught all parties involved by surprise.
- This was caused by heavy rainfall during the day.
- The amount of water was too much for the airport drainage system to handle.
- A runway inspection took place at 21:25z and found RWY 13 operational.
- OO-JAO landed at 21:43z and sustained substantial damage from dirt and debris.



Conclusion

- OUD airport is a fairly dark place at night, a flooded runway is very difficult to see from the cockpit during the (final) approach phase.
- We are convinced that the airport authorities were overwhelmed by events.
- The investigation reveals that the flash flood must have happened a few minutes before landing.
- *Note:*
 - The crew acted in a very professional way, during all phases of this event.
 - The damage was repaired and the aircraft was put back into service.



Flooded airport building



Recommendations

Recommendations

Recommendation I

Accurate runway information must be available to pilots including the flash flood risk information on particular airports.

Recommendation II

Airport authorities must consider the risk of flash flood and develop precautions and adapt emergency response plans accordingly.



Recommendation I

16:27 Ma 13 mei

•••

64%

CCI 02
GMFO - OUD



v 6.4.0.5426



default



CCI

Oujda
Morocco

C-02

28-DEC-2023
OUD-GMFO

• tui GROUP

RUNWAY, TAXIWAY AND AERODROME FACILITIES

Crew may be asked to operate fuel panel.

TAKE-OFF AND DEPARTURE

[787] Takeoff performance may be limited [787]

All SIDs have a climb gradient requirement higher than standard.

Do not enter Algerian airspace below FL100 unless specifically instructed by ATC.

RWY 24: There are no specific SIDs. Be aware of the high climb gradient needed on course to your first enroute waypoint. An alternative routing to the one proposed by ATC might be prudent, especially if the obstacles are not in sight.

SPECIAL CONSIDERATIONS

Flash Flooding

- There may be a delay of up to 2 hours between heavy precipitation in the area and flash flooding affecting the aerodrome.
- No aerodrome flashflood warning system installed.
- Not all of the aerodrome is visible to ATC.
- In case of recent heavy precipitation, request a visual inspection of the runway.
- Be attentive to runway/taxiway conditions and surrounding area.
- At night or with reduced visibility and (recent) precipitation, pay special attention to area's where the RWY or TWY lights are inoperative, as this may be a sign that that area is flooded. If the area of affected lights is in the vicinity of RWY 13 TDZ do not land.
- Runway 13/31 crosses a (dry) riverbed, prone to flashfloods, situated under the last white touchdown zone marking of RWY 13 (i.e. at the end of the touchdown zone).
- If during night operations, runway lights (runway edge and/or center lights) show a gap, especially near the end of the touchdown zone of runway 13, do not land on RWY 13.
- If in doubt, request a runway inspection. Be aware that conditions can change in a matter of minutes.
- In case of uncertainty about flashflood status, especially with (recent) heavy precipitation nearby, divert to the alternate airport.

Changes: Flash Flooding Information added.



THANK YOU

frank.baetens@tuifly.be