

		NTSB ID: DCA02MA026		Aircraft Registration Number: N622BR	
		Occurrence Date: 03/09/2002		Most Critical Injury: None	
		Occurrence Type: Accident		Investigated By: NTSB	
Location/Time					
Nearest City/Place Dulles Airport		State VA	Zip Code	Local Time 1015	Time Zone
Airport Proximity: On Airport/Airstrip		Distance From Landing Facility:			
Aircraft Information Summary					
Aircraft Manufacturer Canadair		Model/Series CL-600-2B19		Type of Aircraft Airplane	
Revenue Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
<p>Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:</p> <p>On March 9, 2002, about 1015 eastern standard time, a Bombardier CL-600-2B19, N622BR, operating as Atlantic Coast Airlines (ACA) flight 7682, struck two wild turkeys while initiating a takeoff from runway 30 at Washington Dulles International Airport (IAD). None of the 3 crewmembers or 50 passengers on board was injured. The airplane sustained damage to the number-two engine inlet, the first officer's windshield, and a 14- by 4-inch section of fuselage skin just below the windshield seal on the first officer's side. Flight 7682 was operating on an instrument flight rules flight plan under the provisions of 14 Code of Federal Regulations (CFR) Part 121 as a regularly scheduled passenger flight from IAD to LaGuardia International Airport, New York, New York. Visual meteorological conditions prevailed at the time of the accident.</p> <p>The captain reported that the airplane was on departure roll and had accelerated past 80 knots when a flock of birds began to fly south over the runway. The airplane was traveling at approximately 110 knots when one of the birds hit the airplane, cracking the first officer's windshield and causing a few shards of glass to fall into the cockpit and onto the first officer. The captain immediately rejected the takeoff and stopped on the runway to assess the damage. The first officer notified air traffic control (ATC) of the rejected takeoff. The flight crew determined that the only damage appeared to be to the windshield, so the captain taxied clear of the runway. The flight crew then notified ATC, ACA operations, and ACA maintenance about the reason for the rejected takeoff and informed them that they were returning to the gate.</p> <p>A postflight inspection by ACA maintenance personnel revealed that the airplane had struck two wild turkeys. One turkey hit the intake of the number-two engine, slightly damaging the forward lip of the engine intake cowl. No bird remains went through the engine. The other turkey hit just below the first officer's windshield, where a turkey leg and foot were still lodged. Closer examination of the airplane revealed that the second turkey hit the nose sheet metal at the base of the first officer's windshield, bending the windshield support structure and causing the windshield to crack upward from that location. The second turkey penetrated the area beneath the lower support structure, went through the pressure bulkhead, and entered the back of the instrument panel but did not penetrate either the windshield or its supporting structure.</p> <p>Title 14 CFR 25.775(b) states,</p> <p>Windshield panes directly in front of the pilots in the normal conduct of their duties, and the supporting structures for these panes, must withstand, without penetration, the impact of a four-pound bird when the velocity of the airplane (relative to the bird along the airplane's flight path) is equal to the value of V_c, at sea level. [V_c equals design cruising speed.]</p> <p>Bombardier Aerospace Company, the manufacturer of the airplane, impact-tested the windshield for a 4-pound bird at 330 knots. The wild turkey that hit the accident airplane was estimated to have weighed roughly 15 pounds, and the impact velocity was approximately 110 knots. Using the kinetic</p>					
FACTUAL REPORT - AVIATION					


 <p>National Transportation Safety Board</p> <p>FACTUAL REPORT</p> <p>AVIATION</p>	NTSB ID: DCA02MA026	
	Occurrence Date: 03/09/2002	
	Occurrence Type: Accident	


Narrative (Continued)

energy equation to calculate the equivalent energy for this mass and speed, investigators determined that the windshield would have been able to withstand the impact of a bird more than twice as large as the turkey that hit the accident aircraft. In this accident, the wild turkey did not penetrate the windshield or its support structure but instead penetrated an area beneath the windshield support structure.

At the time of the accident, IAD had an annual wildlife management plan that included provisions for dispersing and removing wildlife from areas surrounding the aircraft operating area. The United States Department of Agriculture, Animal and Plant Health Inspection Service, Wildlife Services, assessed IAD wildlife hazards for the period from September 2000 to August 2001 [U.S. Department of Agriculture, Animal and Plant Health Inspection Service, Wildlife Services, Monitoring of Potential Wildlife Hazards at Washington Dulles International Airport: September 2000 through August 2001 (Moseley, Virginia)]. The assessment report indicated that, during that time, Wildlife Services took 719 control actions against 36 species, dispersing a total of 19,000 animals (including 3 wild turkeys) and killing a total of 799 animals. The assessment report concluded that birds and mammals continued to present a high risk to aviation safety at IAD and listed several recommendations to reduce the risk, which IAD has implemented. To help eliminate the wild turkey threat, IAD allows airport personnel to hunt wild turkeys within the airport perimeter during the Commonwealth of Virginia's two annual turkey hunting seasons.

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: DCA02MA026				
		Occurrence Date: 03/09/2002				
		Occurrence Type: Accident				
Landing Facility/Approach Information						
Airport Name Dulles International Airport		Airport ID: IAD	Airport Elevation 313 Ft. MSL	Runway Used 30	Runway Length	Runway Width
Runway Surface Type: Asphalt						
Runway Surface Condition: Dry						
Approach/Arrival Flown:						
VFR Approach/Landing:						
Aircraft Information						
Aircraft Manufacturer Canadair		Model/Series CL-600-2B19		Serial Number 7187		
Airworthiness Certificate(s): Transport						
Landing Gear Type: Retractable - Tricycle						
Amateur Built Acft? No		Number of Seats: 50		Certified Max Gross Wt. 51250 LBS	Number of Engines: 2	
Engine Type: Turbo Fan		Engine Manufacturer: General Electric		Model/Series: CF34B		Rated Power: 9220 LBS
- Aircraft Inspection Information						
Type of Last Inspection Continuous Airworthiness		Date of Last Inspection 02/2002		Time Since Last Inspection 203 Hours		Airframe Total Time 12059 Hours
- Emergency Locator Transmitter (ELT) Information						
ELT Installed?/Type Yes /		ELT Operated? No		ELT Aided in Locating Accident Site? No		
Owner/Operator Information						
Registered Aircraft Owner State Street Bank and Trust Co. of CT		Street Address 225 Asylum Street, Goodwin Square				
		City Hartford		State CT	Zip Code 06103	
Operator of Aircraft ATLANTIC COAST AIRLINES		Street Address 45200 Business Court				
		City Dulles		State VA	Zip Code 20166	
Operator Does Business As:				Operator Designator Code: VTZA		
- Type of U.S. Certificate(s) Held:						
Air Carrier Operating Certificate(s): Flag Carrier/Domestic						
Operating Certificate:			Operator Certificate:			
Regulation Flight Conducted Under: Part 121: Air Carrier						
Type of Flight Operation Conducted: Scheduled; Domestic; Passenger Only						
<div style="text-align: center;">FACTUAL REPORT - AVIATION</div> <div style="text-align: right;">Page 2</div>						

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: DCA02MA026							
		Occurrence Date: 03/09/2002							
		Occurrence Type: Accident							
First Pilot Information									
Name		City		State	Date of Birth	Age			
On File									
Sex: F	Seat Occupied: Left	Occupational Pilot?		Certificate Number:					
Certificate(s): Airline Transport; Commercial									
Airplane Rating(s): Multi-engine Land; Single-engine Land									
Rotorcraft/Glider/LTA:									
Instrument Rating(s):									
Instructor Rating(s):									
Current Biennial Flight Review?									
Medical Cert.:		Medical Cert. Status:		Date of Last Medical Exam:					
- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument Actual Simulated	Rotorcraft	Glider	Lighter Than Air
Total Time									
Pilot In Command(PIC)									
Instructor									
Instruction Received									
Last 90 Days									
Last 30 Days									
Last 24 Hours									
Seatbelt Used? Yes		Shoulder Harness Used? Yes		Toxicology Performed? No		Second Pilot? Yes			
Flight Plan/Itinerary									
Type of Flight Plan Filed: IFR									
Departure Point					State	Airport Identifier	Departure Time	Time Zone	
Dulles Airport					VA	KIAD	0000	EST	
Destination					State	Airport Identifier			
					NY	KLGA			
Type of Clearance: IFR									
Type of Airspace:									
Weather Information									
Source of Wx Information:									
FACTUAL REPORT - AVIATION									

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: DCA02MA026			
		Occurrence Date: 03/09/2002			
		Occurrence Type: Accident			

Weather Information					
WOF ID	Observation Time	Time Zone	WOF Elevation <div style="text-align: center;">Ft. MSL</div>	WOF Distance From Accident Site <div style="text-align: center;">NM</div>	Direction From Accident Site <div style="text-align: center;">Deg. Mag.</div>
Sky/Lowest Cloud Condition: Clear			Ft. AGL	Condition of Light: Day	
Lowest Ceiling:			Ft. AGL	Visibility: 9 SM	Altimeter: 30.37 "Hg
Temperature: 14 °C	Dew Point: 14 °C	Weather Conditions at Accident Site: Visual Conditions			
Wind Direction:		Wind Speed: Calm		Wind Gusts:	
Visibility (RVR): Ft.		Visibility (RVV) SM			
Precip and/or Obscuration:					

Accident Information		
Aircraft Damage: Substantial	Aircraft Fire: None	Aircraft Explosion: None

- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL	
First Pilot				1	1	
Second Pilot				1	1	
Student Pilot						
Flight Instructor						
Check Pilot						
Flight Engineer						
Cabin Attendants				1	1	
Other Crew						
Passengers				50	50	
- TOTAL ABOARD -				53	53	
Other Ground						
- GRAND TOTAL -				53	53	



National Transportation Safety Board

FACTUAL REPORT
AVIATION

NTSB ID: DCA02MA026

Occurrence Date: 03/09/2002

Occurrence Type: Accident

Administrative Information

Investigator-In-Charge (IIC)

Lorenda Ward

Additional Persons Participating in This Accident/Incident Investigation: